## **Tour Report**

## Visit to DSP, Durgapur under On Site Learning Opportunity Program

Under OSLO program the following employees of SMS II have visited DSP, Durgapur from 27-10-2022 to 29-10-2022. Objective of the visit was to **"learn the best safety practices at DSP, Durgapur".** 

## Team Members:

- 1. A C Moharana, Sr. Manager, DSO SMS II
- 2. P K Pati, SOST, ZSC Member
- 3. P K Samal, SOST, ZSC Member
- 4. U S Nanda, SOST, ZSC Member

The following points were learned from DSP, Durgapur during the visit;

- A. Department level motivation scheme like "Best Safety Person of the Week".
- B. Guard wall for safety protection in slag dumping and other probable areas.
- C. Anti rope out system in metal carrying cranes
- D. Alert bell switch in cranes before going on to the crane.
- E. Feedback of Fixed type "CO" monitors in control room.
- F. Good practices like Shut down after protocol.
- G. Codification of confined spaces and its display near the area.
- H. Handbook on safety guidelines and rules for contractors.
- I. People are following traffic signals inside plant premises without any supervision
- J. Healthy & informative DSP safety portal with updates at regular intervals

Akhila Chandra Moharana

Sr Manager, DSO – SMS II